EAST Search History

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	59237	"8".clas.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON .	2007/09/04 00:19
L2	51984	"68".clas.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2007/09/04 00:19
L3	21	(L1 or L2) and (pole with chang\$3) and (induction with motor)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2007/09/04 00:19
L4	58	(L1 or L2) and (pole with switch\$4) and (induction with motor)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2007/09/04 00:19
L5	17	(L1 or L2) and (pole with switch\$4) with (dehydration or spinning or drying)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2007/09/04 00:19
L6	0	(L3 or L4 or L5) and @pd>"20070131"	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2007/09/04 00:19
L7	59237	"8".clas.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR .	ON	2007/09/04 00:20
L8	51984	"68".clas.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2007/09/04 00:20
L9	1	(L7 or L8) and (pole with motor) and (voltage with phase) and @pd>"20070131"	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2007/09/04 00:20

EAST Search History

L10	· 59237	"8".clas.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2007/09/04 00:21
L11	51984	"68".clas.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2007/09/04 00:21
L12	1	(L10 or L11) and (pole with motor) and speed and voltage and phase and @pd>"20070131"	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2007/09/04 00:21